

Mechanical Change on Woodpecker Splash guard dust evacuating port.

1.

2.

A technical change took place on the splash guard dust evacuating port.

#2 picture show the out-port being fastened from inside. Because its 1/4" thick flange on the rare occasion interfere with the rotating block, we repositioned it and now we fastening it from the outside. Picture #1.

Dust evacuating port part #2E94024
list price Cnd \$45.75 US \$30.50